



# CONDITION BASED SERVICE (CBS).

## OIL SERVICE.



- Renew engine oil and oil filter
- Check handbrake
- Replace air filter and fuel filter periodically (change cycle depends on model)



### THE 1

|                    |           |
|--------------------|-----------|
| BMW F20 116i       | MUR 7,262 |
| BMW F20 118i       | MUR 7,262 |
| BMW F20LCI 116d ed | MUR 7,646 |
| BMW F20LCI 118i    | MUR 7,518 |
| BMW F40 118i       | MUR 8,061 |
| BMW F70            | MUR 8,061 |

### THE 2

|              |           |
|--------------|-----------|
| BMW F44      | MUR 8,061 |
| BMW F45 218i | MUR 7,518 |
| BMW F74      | MUR 8,061 |
| BMW G42 220d | MUR 8,061 |
| BMW U06 all  | MUR 7,647 |

### THE 3

|                 |           |
|-----------------|-----------|
| BMW F30 316i    | MUR 7,585 |
| BMW F30 320i    | MUR 7,676 |
| BMW F30 320i ED | MUR 7,262 |
| BMW F30 328i    | MUR 7,676 |
| BMW F30LCI 318i | MUR 7,518 |
| BMW F30LCI 320i | MUR 7,906 |
| BMW F30LCI 330i | MUR 8,035 |
| BMW G20 330e    | MUR 8,061 |
| BMW G20 330i    | MUR 7,906 |

### THE 4

|                   |           |
|-------------------|-----------|
| BMW F3X 420i      | MUR 7,676 |
| BMW G22 420d      | MUR 8,061 |
| BMW G22 430i      | MUR 8,061 |
| BMW G22-G23 430d  | MUR 8,061 |
| BMW G22-G23 M440i | MUR 8,061 |
| BMW G23 430i      | MUR 8,061 |

### THE 5

|                   |           |
|-------------------|-----------|
| BMW G30 520i      | MUR 8,061 |
| BMW G30 530i-530e | MUR 8,061 |
| BMW G30 LCI 520i  | MUR 8,061 |
| BMW G30 LCI 530e  | MUR 8,061 |
| BMW G60 520i-530e | MUR 8,061 |

### THE 7

|                    |           |
|--------------------|-----------|
| BMW G11, G12 740e  | MUR 8,682 |
| BMW G12 LCI 745LeX | MUR 8,682 |
| BMW G70 740d       | MUR 8,061 |

### THE 8

|              |           |
|--------------|-----------|
| BMW G16 840d | MUR 8,061 |
| BMW G16 840i | MUR 8,061 |

### THE X1

|                        |           |
|------------------------|-----------|
| BMW F48 18i, 20i       | MUR 7,518 |
| BMW F48 LCI 18i        | MUR 8,061 |
| BMW F48, F39 LCI 25 eX | MUR 8,061 |
| BMW U11 18i            | MUR 7,647 |
| BMW U11 20i            | MUR 7,647 |
| BMW U11 23i            | MUR 8,035 |
| BMW U11 25e            | MUR 7,647 |

### THE X2

|             |           |
|-------------|-----------|
| BMW F39 18i | MUR 7,906 |
| BMW F39 20i | MUR 7,906 |

### THE X3

|                       |           |
|-----------------------|-----------|
| BMW F25 20d           | MUR 7,641 |
| BMW F25 28i N20       | MUR 7,572 |
| BMW F25 28i N52       | MUR 8,452 |
| BMW F25 30d           | MUR 8,314 |
| BMW G01 30e           | MUR 8,035 |
| BMW G01 LCI 20iX      | MUR 8,035 |
| BMW G01 M40i          | MUR 9,044 |
| BMW G01, G02 20i      | MUR 8,061 |
| BMW G01, G02 30i      | MUR 8,061 |
| BMW G01LCI 18d        | MUR 8,061 |
| BMW G01LCI 20d        | MUR 8,061 |
| BMW G01LCI xDrive30e  | MUR 8,035 |
| BMW G01LCI-G02LCI 30d | MUR 8,061 |
| BMW G45 20xDrive      | MUR 8,061 |
| BMW G45 30e           | MUR 8,061 |
| BMW G45 M50           | MUR 8,061 |

Price includes: Materials, Labour and VAT. Exchange rate: MUR 55 / EUR 1. All offers are based on rate mentioned above and subject to change based on currency fluctuations higher than 10%. Subject to error, misprint and alteration. Photo non-contractual. Validity: 31.12.2026

Leal & Co. Ltd

Motorway M1, Pailles 11201 | Tel: 207 2454 / 207 2400 | Fax: 286 5541

E-Mail: [bmwcustomerservice@lealgroup.mu](mailto:bmwcustomerservice@lealgroup.mu)



# CONDITION BASED SERVICE (CBS).

## OIL SERVICE.



- Renew engine oil and oil filter
- Check handbrake
- Replace air filter and fuel filter periodically (change cycle depends on model)



### THE X4

|                  |           |
|------------------|-----------|
| BMW F26 20iX     | MUR 7,572 |
| BMW F26 28iX     | MUR 7,572 |
| BMW G02 LCI 20iX | MUR 8,035 |
| BMW G02LCI 30i   | MUR 8,035 |

### THE i3

|             |           |
|-------------|-----------|
| BMW I01 I3  | MUR 7,577 |
| BMW I01 I3S | MUR 6,566 |

### THE X5

|                |           |
|----------------|-----------|
| BMW F15 25d(X) | MUR 8,184 |
| BMW F15 30dX   | MUR 8,872 |
| BMW F15 40e    | MUR 7,676 |
| BMW G05 30D    | MUR 8,757 |
| BMW G05 40i    | MUR 7,906 |
| BMW G05 45e    | MUR 8,682 |
| BMW G05 M50D   | MUR 8,757 |
| BMW G05LCI 30d | MUR 8,061 |
| BMW G05LCI 50e | MUR 8,035 |

### THE X6

|              |           |
|--------------|-----------|
| BMW F16 30dX | MUR 9,550 |
| BMW F16 40dX | MUR 9,550 |
| BMW G06 40iX | MUR 8,682 |

### THE X7

|                 |           |
|-----------------|-----------|
| BMW G07 M50d    | MUR 8,061 |
| BMW G07 M50i    | MUR 6,566 |
| BMW G07LCI 30d  | MUR 8,061 |
| BMW G07LCI 40d  | MUR 8,061 |
| BMW G07LCI 40i  | MUR 8,061 |
| BMW G07LCI M60i | MUR 6,566 |

Price includes: Materials, Labour and VAT. Exchange rate: MUR 55 / EUR 1. All offers are based on rate mentioned above and subject to change based on currency fluctuations higher than 10%. Subject to error, misprint and alteration. Photo non-contractual. Validity: 31.12.2026