



CONDITION BASED SERVICE (CBS).

REAR BRAKE SERVICE.



- Replace brake pads and wear sensor
- Clean calliper cavities
- Replace brake disc if worn to recommended change point



THE 1

BMW F20 116i	MUR 15,158
BMW F20 118i	MUR 15,539
BMW F20LCI 116d ed	MUR 15,920
BMW F20LCI 118i	MUR 15,158
BMW F40 118i	MUR 16,344
BMW F70	MUR 17,379

THE 2

BMW F44	MUR 16,344
BMW F45 218i	MUR 16,344
BMW F74	MUR 17,379
BMW G42 220d	MUR 16,574
BMW U06 all	MUR 17,379

THE 3

BMW F30 316i	MUR 15,920
BMW F30 320i	MUR 15,158
BMW F30 320i ED	MUR 15,158
BMW F30 328i	MUR 15,158
BMW F30LCI 318i	MUR 15,158
BMW F30LCI 320i	MUR 15,158
BMW F30LCI 330i	MUR 15,158
BMW G20 330e	MUR 17,034
BMW G20 330i	MUR 28,038

THE 4

BMW F3X 420i	MUR 15,158
BMW G22 420d	MUR 16,574
BMW G22 430i	MUR 18,874
BMW G22-G23 430d	MUR 18,874
BMW G22-G23 M440i	MUR 18,874
BMW G23 430i	MUR 18,874

THE 5

BMW G30 520i	MUR 17,379
BMW G30 530i,530e	MUR 28,304
BMW G30 LCI 520i	MUR 17,149
BMW G30 LCI 530e	MUR 28,074
BMW G60 520i-530e	MUR 17,724

THE 7

BMW G11, G12 740e	MUR 18,759
BMW G12 LCI 745LeX	MUR 18,759
BMW G70 740d	MUR 23,819

THE 8

BMW G16 840d	MUR 18,759
BMW G16 840i	MUR 18,759

THE X1

BMW F48 18i,20i	MUR 15,963
BMW F48 LCI 18i	MUR 16,344
BMW F48, F39 LCI 25 eX	MUR 16,344
BMW U11 18i	MUR 17,379
BMW U11 20i	MUR 17,379
BMW U11 23i	MUR 17,379
BMW U11 25e	MUR 17,379

THE X2

BMW F39 18i	MUR 16,344
BMW F39 20i	MUR 16,344

THE X3

BMW F25 20d	MUR 16,229
BMW F25 28i N20	MUR 16,229
BMW F25 28i N52	MUR 16,229
BMW F25 30d	MUR 16,229
BMW G01 30e	MUR 17,034
BMW G01 LCI 20iX	MUR 16,804
BMW G01 M40i	MUR 18,414
BMW G01,G02 20i	MUR 17,034
BMW G01,G02 30i	MUR 17,034
BMW G01LCI 18d	MUR 16,804
BMW G01LCI 20d	MUR 18,414
BMW G01LCI xDrive30e	MUR 18,414
BMW G01LCI-G02LCI 30d	MUR 18,414
BMW G45 20xDrive	MUR 17,034
BMW G45 30e	MUR 15,424
BMW G45 M50	MUR 17,034

Price includes: Materials, Labour and VAT. Exchange rate: MUR 55 / EUR 1. All offers are based on rate mentioned above and subject to change based on currency fluctuations higher than 10%. Subject to error, misprint and alteration. Photo non-contractual. Validity: 31.12.2026

Leal & Co. Ltd

Motorway M1, Pailles 11201 | Tel: 207 2454 / 207 2400 | Fax: 286 5541

E-Mail: bmwcustomerservice@lealgroup.mu



CONDITION BASED SERVICE (CBS).

REAR BRAKE SERVICE.



- Replace brake pads and wear sensor
- Clean calliper cavities
- Replace brake disc if worn to recommended change point



THE X4

BMW F26 20iX	MUR 16,229
BMW F26 28iX	MUR 16,229
BMW G02 LCI 20iX	MUR 18,414
BMW G02LCI 30i	MUR 16,804

THE X5

BMW F15 25d(X)	MUR 19,055
BMW F15 30dX	MUR 19,055
BMW F15 40e	MUR 17,149
BMW G05 30D	MUR 20,320
BMW G05 40i	MUR 18,414
BMW G05 45e	MUR 18,414
BMW G05 M50D	MUR 20,320
BMW G05LCI 30d	MUR 18,414
BMW G05LCI 50e	MUR 18,414

THE X6

BMW F16 30dX	MUR 19,733
BMW F16 40dX	MUR 19,733
BMW G06 40iX	MUR 18,414

THE X7

BMW G07 M50d	MUR 18,414
BMW G07 M50i	MUR 22,209
BMW G07LCI 30d	MUR 18,414
BMW G07LCI 40d	MUR 18,414
BMW G07LCI 40i	MUR 18,414
BMW G07LCI M60i	MUR 22,209

THE i3

BMW I01 I3	MUR 16,344
BMW I01 I3S	MUR 16,344

THE i4

BMW G26 i4 40	MUR 17,034
BMW G26 i4 M50-eDrive35	MUR 18,874

THE i5

BMW G60 i5 eDrive40	MUR 24,497
BMW G60 i5 M60	MUR 24,497

THE i7

BMW G70 i7 xDrive60-eDrive50	MUR 24,497
------------------------------	------------

THE iX1

BMW iX1 eDrive20	MUR 17,379
BMW iX1 xDrive30	MUR 17,379

THE iX2

BMW U10 sDrive 20i	MUR 17,379
--------------------	------------

THE iX3

BMW G08LCI BEV	MUR 17,185
----------------	------------

THE iX40

BMW I20 iX40	MUR 18,795
--------------	------------

THE iX50

BMW I20 iX50	MUR 18,795
--------------	------------

Price includes: Materials, Labour and VAT. Exchange rate: MUR 55 / EUR 1. All offers are based on rate mentioned above and subject to change based on currency fluctuations higher than 10%. Subject to error, misprint and alteration. Photo non-contractual. Validity: 31.12.2026

Leal & Co. Ltd

Motorway M1, Pailles 11201 | Tel: 207 2454 / 207 2400 | Fax: 286 5541
E-Mail: bmwcustomerservice@lealgroup.mu