



CONDITION BASED SERVICE (CBS).

SPARK PLUGS.



- Replace spark plugs
- To ensure optimum performance, fuel economy and low emissions.



THE 1

BMW F20 116i	MUR 9,320
BMW F20 118i	MUR 9,701
BMW F20LCI 118i	MUR 10,839
BMW F40 118i	MUR 10,161
BMW F70	MUR 9,701

THE 2

BMW F44	MUR 10,161
BMW F45 218i	MUR 8,170
BMW F74	MUR 9,701
BMW U06 all	MUR 7,825

THE 3

BMW F30 316i	MUR 10,083
BMW F30 320i	MUR 11,989
BMW F30 320i ED	MUR 11,989
BMW F30 328i	MUR 11,989
BMW F30LCI 318i	MUR 10,839
BMW F30LCI 320i	MUR 12,449
BMW F30LCI 330i	MUR 12,449
BMW G20 330e	MUR 10,161
BMW G20 330i	MUR 12,449

THE 4

BMW F3X 420i	MUR 11,989
BMW G22 430i	MUR 10,161
BMW G22-G23 M440i	MUR 13,381
BMW G23 430i	MUR 10,161

THE 5

BMW G30 520i	MUR 10,161
BMW G30 530i,530e	MUR 10,161
BMW G30 LCI 520i	MUR 10,161
BMW G30 LCI 530e	MUR 10,161
BMW G60 520i-530e	MUR 9,701

THE 7

BMW G11, G12 740e	MUR 10,543
BMW G12 LCI 745LeX	MUR 10,543

THE 8

BMW G16 840i	MUR 13,381
--------------	------------

THE X1

BMW F48 18i,20i	MUR 8,170
BMW F48 LCI 18i	MUR 10,161
BMW F48, F39 LCI 25 eX	MUR 10,161
BMW U11 18i	MUR 7,825
BMW U11 20i	MUR 7,825
BMW U11 23i	MUR 9,701
BMW U11 25e	MUR 7,825

THE X2

BMW F39 18i	MUR 8,551
BMW F39 20i	MUR 10,161

THE X3

BMW F25 28i N20	MUR 10,083
BMW F25 28i N52	MUR 13,073
BMW G01 30e	MUR 10,161
BMW G01 LCI 20iX	MUR 10,161
BMW G01 M40i	MUR 10,543
BMW G01,G02 20i	MUR 10,161
BMW G01,G02 30i	MUR 10,161
BMW G01LCI xDrive30e	MUR 10,161
BMW G45 20xDrive	MUR 9,701
BMW G45 30e	MUR 9,701
BMW G45 M50	MUR 9,701

THE X4

BMW F26 20iX	MUR 9,701
BMW F26 28iX	MUR 10,083
BMW G02 LCI 20iX	MUR 10,161
BMW G02LCI 30i	MUR 10,161

THE X5

BMW F15 40e	MUR 9,701
BMW G05 40i	MUR 10,161
BMW G05 45e	MUR 10,543
BMW G05LCI 50e	MUR 12,691

Price includes: Materials, Labour and VAT. Exchange rate: MUR 55 / EUR 1. All offers are based on rate mentioned above and subject to change based on currency fluctuations higher than 10%. Subject to error, misprint and alteration. Photo non-contractual. Validity: 31.12.2026

Leal & Co. Ltd

Motorway M1, Pailles 11201 | Tel: 207 2454 / 207 2400 | Fax: 286 5541

E-Mail: bmwcustomerservice@lealgroup.mu



CONDITION BASED SERVICE (CBS).

SPARK PLUGS.



- Replace spark plugs
- To ensure optimum performance, fuel economy and low emissions.



THE X6

BMW G06 40iX MUR 10,543

THE X7

BMW G07 M50i MUR 9,701
BMW G07LCI 40i MUR 9,701
BMW G07LCI M60i MUR 9,701

THE i3

BMW I01 I3 MUR 8,079
BMW I01 I3S MUR 3,721

THE iX2

BMW U10 sDrive 20i MUR 7,825

THE iX3

BMW G08LCI BEV MUR 3,721

THE iX40

BMW I20 iX40 MUR 3,721

Price includes: Materials, Labour and VAT. Exchange rate: MUR 55 / EUR 1. All offers are based on rate mentioned above and subject to change based on currency fluctuations higher than 10%. Subject to error, misprint and alteration. Photo non-contractual. Validity: 31.12.2026

Leal & Co. Ltd

Motorway M1, Pailles 11201 | Tel: 207 2454 / 207 2400 | Fax: 286 5541

E-Mail: bmwcustomerservice@lealgroup.mu