



CONDITION BASED SERVICE (CBS).

OIL SERVICE



- Engine Oil and Oil Filter changed
- Check Handbrake
- Air Filter and Fuel Filter replaced periodically (change cycle depends on model)



BMW 1 Series

BMW 1 Series F20 (116d ED LCI)	MUR 5,840
BMW 1 Series F20 (118i LCI)	MUR 5,463
BMW 1 Series F20 (116i, 118i)	MUR 5,497
BMW 1 Series F40 (118i)	MUR 6,049

BMW 2 Series

BMW 2 Series F45 (218i)	MUR 5,687
-------------------------	-----------

BMW 3 Series

BMW 3 Series F30 (318i LCI)	MUR 5,687
BMW 3 Series F30 (320i LCI)	MUR 5,946
BMW 3 Series F30 (330i LCI)	MUR 6,032
BMW 3 Series F30 (316i)	MUR 5,514
BMW 3 Series F30 (320i ED)	MUR 5,497
BMW 3 Series F30 (320i, 328i)	MUR 5,773
BMW 3 Series G20 (330i)	MUR 5,934

BMW 4 Series

BMW 4 Series F3X (420i)	MUR 5,773
-------------------------	-----------

BMW 5 Series

BMW 5 Series G30 (520i, 530i, 530e)	MUR 6,049
-------------------------------------	-----------

BMW X1

BMW X1 F48 (18i, 20i)	MUR 5,687
BMW X1 F49 (18i, 20i)	MUR 5,687

BMW X2

BMW X2 F39 (18i, 20i)	MUR 5,946
-----------------------	-----------

BMW X3

BMW X3 F25 (28i N52)	MUR 6,291
BMW X3 F25 (28i N20)	MUR 5,704
BMW X3 G01 (20i, 30i)	MUR 6,049
BMW X3 F25 (20d)	MUR 5,411
BMW X3 F25 (30d)	MUR 5,859

BMW X4

BMW X4 F26 (20i, 28i)	MUR 5,704
BMW X4 G02 (20i, 30i)	MUR 6,049

BMW X5

BMW X5 F15 (40e)	MUR 5,773
BMW X5 F15 (25d)	MUR 6,249
BMW X5 F15 (30d)	MUR 6,728
BMW X5 G05 (40i)	MUR 5,946
BMW X5 G05 (M50d, 30d)	MUR 6,118
BMW X5 G05 (45e)	MUR 6,463

BMW X6

BMW X6 F16 (30d, 40d)	MUR 7,337
-----------------------	-----------

Price includes: Materials, Labour and VAT. Exchange rate: MUR 51.50 / EUR 1. All offers are based on rate mentioned above and subject to change based on currency fluctuations higher than 10%. Subject to error, misprint and alteration. Photo non-contractual. Validity: 31.12.21

Leal & Co. Ltd

Motorway M1, Pailles 11201
Tel: 207 2454 / 207 2400 | Fax: 286 5541
E-Mail: bmwcustomerservice@lealgroup.mu