



# CONDITION BASED SERVICE (CBS).

## FRONT BRAKES



- Replace Brake Pads and Wear Sensor
- Clean Caliper Cavities
- Replace Brake Disc if worn to recommended point (additional charges applicable)



### BMW 1 Series

|                                |            |
|--------------------------------|------------|
| BMW 1 Series F20 (116d ED LCI) | MUR 14,939 |
| BMW 1 Series F20 (118i LCI)    | MUR 14,709 |
| BMW 1 Series F20 (116i)        | MUR 14,709 |
| BMW 1 Series F20 (118i)        | MUR 15,744 |
| BMW 1 Series F40 (118i)        | MUR 17,239 |

### BMW 2 Series

|                         |            |
|-------------------------|------------|
| BMW 2 Series F45 (218i) | MUR 16,836 |
|-------------------------|------------|

### BMW 3 Series

|                                       |            |
|---------------------------------------|------------|
| BMW 3 Series F30 (318i LCI, 320i LCI) | MUR 15,514 |
| BMW 3 Series F30 (330i LCI)           | MUR 16,434 |
| BMW 3 Series F30 (316i)               | MUR 15,744 |
| BMW 3 Series F30 (320i ED, 320i)      | MUR 15,514 |
| BMW 3 Series F30 (328i)               | MUR 16,434 |
| BMW 3 Series G20 (330i)               | MUR 40,986 |

### BMW 4 Series

|                         |            |
|-------------------------|------------|
| BMW 4 Series F3X (420i) | MUR 15,514 |
|-------------------------|------------|

### BMW 5 Series

|                               |            |
|-------------------------------|------------|
| BMW 5 Series G30 (520i)       | MUR 17,526 |
| BMW 5 Series G30 (530i, 530e) | MUR 25,461 |

### BMW X1

|                             |            |
|-----------------------------|------------|
| BMW X1 F48   F49 (18i, 20i) | MUR 16,606 |
|-----------------------------|------------|

### BMW X2

|                       |            |
|-----------------------|------------|
| BMW X2 F39 (18i, 20i) | MUR 16,606 |
|-----------------------|------------|

### BMW X3

|                               |            |
|-------------------------------|------------|
| BMW X3 F25 (28i N52, 28i N20) | MUR 18,389 |
| BMW X3 G01 (20i)              | MUR 17,239 |
| BMW X3 G01 (30i)              | MUR 25,174 |
| BMW X3 F25 (20d, 30d)         | MUR 18,095 |

### BMW X4

|                  |            |
|------------------|------------|
| BMW X4 F26 (20i) | MUR 18,389 |
| BMW X4 F26 (28i) | MUR 33,339 |
| BMW X4 G02 (20i) | MUR 17,239 |
| BMW X4 G02 (30i) | MUR 25,174 |
| BMW X5 G05 (45e) | MUR 29,774 |

### BMW X5

|                            |            |
|----------------------------|------------|
| BMW X5 F15 (40e, 25d, 30d) | MUR 19,803 |
| BMW X5 G05 (40i)           | MUR 45,989 |
| BMW X5 G05 (M50d)          | MUR 45,874 |
| BMW X5 G05 (30d)           | MUR 70,311 |

### BMW X6

|                       |            |
|-----------------------|------------|
| BMW X6 F16 (30d, 40d) | MUR 20,551 |
|-----------------------|------------|

Price includes: Materials, Labour and VAT. Exchange rate: MUR 51.50 / EUR 1. All offers are based on rate mentioned above and subject to change based on currency fluctuations higher than 10%. Subject to error, misprint and alteration. Photo non-contractual. Validity: 31.12.21

#### Leal & Co. Ltd

Motorway M1, Pailles 11201

Tel: 207 2454 / 207 2400 | Fax: 286 5541

E-Mail: bmwcustomerservice@lealgroup.mu