



CONDITION BASED SERVICE (CBS).

REAR BRAKES



- Replace Brake Pads and Wear Sensor
- Clean Calliper Cavities
- Replace Brake Disc if worn to recommended change point



BMW 1 Series

BMW 1 Series F20 (116d ED LCI)	MUR 13,961
BMW 1 Series F20 (118i LCI)	MUR 13,501
BMW 1 Series F20 (116i)	MUR 13,501
BMW 1 Series F20 (118i)	MUR 13,731
BMW 1 Series F40 (118i)	MUR 15,111

BMW 2 Series

BMW 2 Series F45 (218i)	MUR 15,111
-------------------------	------------

BMW 3 Series

BMW 3 Series F30 (318i LCI)	MUR 13,501
BMW 3 Series F30 (320i LCI)	MUR 13,501
BMW 3 Series F30 (330i LCI)	MUR 13,501
BMW 3 Series F30 (316i)	MUR 13,961
BMW 3 Series F30 (320i ED)	MUR 13,501
BMW 3 Series F30 (320i, 328i)	MUR 13,501
BMW 3 Series G20 (330i)	MUR 25,231

BMW 4 Series

BMW 4 Series F3X (420i)	MUR 13,501
-------------------------	------------

BMW 5 Series

BMW 5 Series G30 (520i, 530i, 530e)	MUR 16,146
-------------------------------------	------------

BMW X1

BMW X1 F48 (18i, 20i)	MUR 14,881
BMW X1 F49 (18i, 20i)	MUR 14,881

BMW X2

BMW X2 F39 (18i, 20i)	MUR 15,111
-----------------------	------------

BMW X3

BMW X3 F25 (28i N52, 28i N20)	MUR 14,479
BMW X3 G01 (20i, 30i)	MUR 15,859
BMW X3 F25 (20d)	MUR 14,168
BMW X3 F25 (30d)	MUR 14,168

BMW X4d)

BMW X4 F26 (20i, 28i)	MUR 14,479
BMW X4 G02 (20i, 30i)	MUR 15,859

BMW X5

BMW X5 F15 (40e)	MUR 13,674
BMW X5 F15 (25d, 30d)	MUR 14,824
BMW X5 G05 (40i)	MUR 15,571
BMW X5 G05 (M50d, 30d)	MUR 16,721
BMW X5 G05 (45e)	MUR 15,751

BMW X6

BMW X6 F16 (30d, 40d)	MUR 15,433
-----------------------	------------

Price includes: Materials, Labour and VAT. Exchange rate: MUR 51.50 / EUR 1. All offers are based on rate mentioned above and subject to change based on currency fluctuations higher than 10%. Subject to error, misprint and alteration. Photo non-contractual. Validity: 31.12.21

Leal & Co. Ltd

Motorway M1, Pailles 11201

Tel: 207 2454 / 207 2400 | Fax: 286 5541

E-Mail: bmwcustomerservice@lealgroup.mu