



CONDITION BASED SERVICE (CBS).

SPARK PLUGS



- Replace Spark Plugs.
- To ensure optimum performance, fuel economy and low emissions.



BMW 1 Series

BMW 1 Series F20 (118i LCI)	MUR 8,556
BMW 1 Series F20 (116i)	MUR 7,981
BMW 1 Series F20 (118i)	MUR 8,211
BMW 1 Series F40 (118i)	MUR 8,671

BMW 2 Series

BMW 2 Series F45 (218i)	MUR 6,946
-------------------------	-----------

BMW 3 Series

BMW 3 Series F30 (316i)	MUR 8,441
BMW 3 Series F30 (318i LCI)	MUR 8,556
BMW 3 Series F30 (320i LCI, 330i LCI)	MUR 10,051
BMW 3 Series F30 (320i, 320iED, 328i)	MUR 9,591
BMW 3 Series G20 (330i)	MUR 9,591

BMW 4 Series

BMW 4 Series F3X (420i)	MUR 9,591
-------------------------	-----------

BMW 5 Series

BMW 5 Series G30 (520i, 530i, 530e)	MUR 8,671
-------------------------------------	-----------

BMW X1

BMW X1 F48 (18i, 20i)	MUR 6,946
BMW X1 F49 (18i,20i)	MUR 6,946

BMW X2

BMW X2 F39 (18i)	MUR 7,176
BMW X2 F39 (20i)	MUR 8,671

BMW X3

BMW X3 F25 (28i N52)	MUR 11,201
BMW X3 F25 (28i N20)	MUR 8,441
BMW X3 G01 (20i,30i)	MUR 8,671

BMW X4

BMW X4 F26 (20i)	MUR 8,211
BMW X4 F26 (28i)	MUR 8,441
BMW X4 G02 (20i, 30i)	MUR 8,671

BMW X5

BMW X5 F15 (40e)	MUR 8,211
BMW X5 G05 (40i)	MUR 8,671
BMW X5 G05 (45e)	MUR 8,901

Price includes: Materials, Labour and VAT. Exchange rate: MUR 51.50 / EUR 1. All offers are based on rate mentioned above and subject to change based on currency fluctuations higher than 10%. Subject to error, misprint and alteration. Photo non-contractual. Validity: 31.12.21

Leal & Co. Ltd

Motorway M1, Pailles 11201

Tel: 207 2454 / 207 2400 | Fax: 286 5541

E-Mail: bmwcustomerservice@lealgroup.mu