



CONDITION BASED SERVICE (CBS).

VEHICLE CHECK

Check Condition of Vehicle Systems including



- Exterior panelling and underbody for corrosion and damage
- Tyres, Steering and Shock Absorbers
- Electrical Systems including Battery, Headlights and Indication Field Lighting
- Safety including Brakes and Seat Belts
- Check Coolant and Fluid Levels



BMW 1 Series

BMW 1 Series F20 (116d ED LCI, 116i)	MUR 3,151
BMW 1 Series F20 (118i LCI, 118i)	MUR 3,151
BMW 1 Series F40 (118i)	MUR 3,151

BMW 2 Series

BMW 2 Series F45 (218i)	MUR 3,151
-------------------------	-----------

BMW 3 Series

BMW 3 Series F30 (318i LCI)	MUR 3,151
BMW 3 Series F30 (320i LCI)	MUR 3,151
BMW 3 Series F30 (330i LCI)	MUR 3,151
BMW 3 Series F30 (316i)	MUR 3,611
BMW 3 Series F30 (320i ED, 320i, 328i)	MUR 3,151
BMW 3 Series G20 (330i)	MUR 3,151

BMW 4 Series

BMW 4 Series F3X (420i)	MUR 3,151
-------------------------	-----------

BMW 5 Series

BMW 5 Series G30 (520i, 530i, 530e)	MUR 3,151
-------------------------------------	-----------

BMW X1

BMW X1 F48 (18i, 20i)	MUR 3,151
BMW X1 449 (18i, 20i)	MUR 3151

BMW X2

BMW X2 F39 (18i, 20i)	MUR 3,151
-----------------------	-----------

BMW X3

BMW X3 F25 (28i N52, 28i N20)	MUR 3,151
BMW X3 G01 (20i, 30i)	MUR 3,151
BMW X3 F25 (20d, 30d)	MUR 2,875

BMW X4

BMW X4 F26 (20i, 28i)	MUR 3,151
BMW X4 G02 (20i, 30i)	MUR 3,151

BMW X5

BMW X5 F15 (40e)	MUR 3,381
BMW X5 F15 (25d, 30d)	MUR 3,151
BMW X5 G05 (40i)	MUR 3,381
BMW X5 G05 (M50d, 30d)	MUR 3,151
BMW X5 G05 (45e)	MUR 3,151

BMW X6

MUR 3,761

Price includes: Materials, Labour and VAT. Exchange rate: MUR 51.50 / EUR 1. All offers are based on rate mentioned above and subject to change based on currency fluctuations higher than 10%. Subject to error, misprint and alteration. Photo non-contractual. Validity: 31.12.21

Leal & Co. Ltd

Motorway M1, Pailles 11201
Tel: 207 2454 / 207 2400 | Fax: 286 5541
E-Mail: bmwcustomerservice@lealgroup.mu