



# CONDITION BASED SERVICE (CBS).

## REAR BRAKES.



- Replace brake pads and wear sensor
- Clean calliper cavities
- Replace brake disc if worn to recommended change point



### BMW 1 Series

BMW 1 Series F20 (116d ED LCI)	MUR 14,162
BMW 1 Series F20 (118i LCI)	MUR 13,679
BMW 1 Series F20 (116i)	MUR 13,679
BMW 1 Series F20 (118i)	MUR 13,921
BMW 1 Series F40 (118i)	MUR 13,346

### BMW 2 Series

BMW 2 Series F44	MUR 14,381
BMW 2 Series F45 (218i)	MUR 15,301

### BMW 3 Series

BMW 3 Series F30 (318i LCI)	MUR 13,679
BMW 3 Series F30 (320i LCI)	MUR 13,679
BMW 3 Series F30 (330i LCI)	MUR 13,679
BMW 3 Series F30 (316i)	MUR 14,162
BMW 3 Series F30 (320i ED)	MUR 13,679
BMW 3 Series F30 (320i, 328i)	MUR 13,679
BMW 3 Series G20 (330i)	MUR 24,604
BMW 3 Series G20 (330e)	MUR 14,496

### BMW i3 Series

BMW i3 Series I01 (i3)	MUR 14,691
BMW i3 Series I01 (i3S)	MUR 14,208

### BMW 4 Series

BMW 4 Series F3X (420i)	MUR 13,679
BMW 4 Series G22	MUR 16,221

### BMW 5 Series

BMW 5 Series G30 (520i)	MUR 16,336
BMW 5 Series G30 (530i, 530e)	MUR 16,336
BMW 5 Series G30 (520i LCI, 330e LCI)	MUR 15,186

### BMW 7 Series

BMW 7 Series G11 (740e)	MUR 16,451
BMW 7 Series G12 (740e)	MUR 16,451
BMW 7 Series G12 (745LeX LCI)	MUR 15,071

### BMW X1

BMW X1 F48 (18i, 20i)	MUR 15,059
BMW X1 F48 (18i LCI)	MUR 15,301
BMW X1 F48 (25eX LCI)	MUR 15,979

### BMW X2

BMW X2 F39 (18i, 20i)	MUR 15,301
BMW X2 F39 (25eX LCI)	MUR 15,979

### BMW X3

BMW X3 F25 (28i N52, 28i N20)	MUR 14,668
BMW X3 G01 (20i, 30i)	MUR 16,048
BMW X3 G01 (20iX LCI, 30eX LCI)	MUR 14,898
BMW X3 G01 (30e)	MUR 16,048
BMW X3 G01 (M40i)	MUR 16,163
BMW X3 F25 (20d, 30d)	MUR 14,185

### BMW iX3

BMW G08 (BEV LCI)	MUR 15,140
-------------------	------------

### BMW X4

BMW X4 F26 (20ix, 28ix)	MUR 14,668
BMW X4 G02 (20i, 30i)	MUR 16,048
BMW X4 G02 (20iX LCI)	MUR 16,163

### BMW X5

BMW X5 F15 (40e)	MUR 13,863
BMW X5 F15 (25dx, 30dx)	MUR 15,071
BMW X5 G05 (40i)	MUR 15,761
BMW X5 G05 (30dx)	MUR 16,968
BMW X5 G05 (M50d)	MUR 16,968
BMW X5 G05 (45e)	MUR 15,761

### BMW X6

BMW X6 F16 (30dx, 40dx)	MUR 15,709
BMW X6 G06 (40iX)	MUR 15,761

### BMW iX

BMW I20 (ix40)	MUR 16,060
----------------	------------

Price includes: Materials, Labour and VAT. Exchange rate: MUR 51 / EUR 1. All offers are based on rate mentioned above and subject to change based on currency fluctuations higher than 10%. Subject to error, misprint and alteration. Photo non-contractual. Validity: 30.06.23