



CONDITION BASED SERVICE (CBS).

VEHICLE CHECK.



- Check exterior panelling and underbody for corrosion and damage
- Check tyres, steering and shock absorbers
- Check electrical systems including battery, headlights and indication field lighting
- Check safety including brakes and seat belts
- Check coolant and fluid levels



BMW 1 Series

BMW 1 Series F20 (116d ED LCI)	MUR 3,318
BMW 1 Series F20 (118i LCI)	MUR 3,318
BMW 1 Series F20 (116i, 118i)	MUR 3,318
BMW 1 Series F40 (118i)	MUR 3,318

BMW 2 Series

BMW 2 Series F44	MUR 3,318
BMW 2 Series F45 (218i)	MUR 3,318

BMW 3 Series

BMW 3 Series F30 (318i LCI)	MUR 3,318
BMW 3 Series F30 (320i LCI)	MUR 3,318
BMW 3 Series F30 (330i LCI)	MUR 3,318
BMW 3 Series F30 (316i)	MUR 3,801
BMW 3 Series F30 (320i ED)	MUR 3,318
BMW 3 Series F30 (320i, 328i)	MUR 3,318
BMW 3 Series G20 (330i)	MUR 3,318
BMW 3 Series G20 (330e)	MUR 3,318

BMW i3 Series

BMW i3 Series I01 (i3)	MUR 3,559
BMW i3 Series I01 (i3S)	MUR 3,559

BMW 4 Series

BMW 4 Series F3X (420i)	MUR 3,318
BMW 4 Series G22	MUR 3,318

BMW 5 Series

BMW 5 Series G30 (520i)	MUR 3,318
BMW 5 Series G30 (530i, 530e)	MUR 3,318
BMW 5 Series G30 (520i LCI, 330e LCI)	MUR 3,318

BMW 7 Series

BMW 7 Series G11 (740e)	MUR 3,559
BMW 7 Series G12 (740e, 745LeX LCI)	MUR 3,559

BMW X1

BMW X1 F48 (18i, 20i)	MUR 3,318
BMW X1 F48 (18i LCI)	MUR 3,318
BMW X1 F48 (25eX LCI)	MUR 3,318

BMW X2

BMW X2 F39 (18i, 20i)	MUR 3,318
BMW X2 F39 (25eX LCI)	MUR 3,318

BMW X3

BMW X3 F25 (28i N52, 28i N20)	MUR 3,318
BMW X3 G01 (20i, 30i)	MUR 3,318
BMW X3 G01 (20iX LCI, 30eX LCI)	MUR 3,559
BMW X3 G01 (30e)	MUR 3,559
BMW X3 G01 (M40i)	MUR 3,318
BMW X3 F25 (20d, 30d)	MUR 2,892

BMW iX3

BMW G08 (BEV LCI)	MUR 2,593
-------------------	-----------

BMW X4

BMW X4 F26 (20ix, 28ix)	MUR 3,318
BMW X4 G02 (20i, 30i)	MUR 3,318
BMW X4 G02 (20iX LCI)	MUR 3,318

BMW X5

BMW X5 F15 (40e)	MUR 3,559
BMW X5 F15 (25dx, 30dx)	MUR 3,318
BMW X5 G05 (40i)	MUR 3,559
BMW X5 G05 (30dx)	MUR 3,318
BMW X5 G05 (M50d)	MUR 3,318
BMW X5 G05 (45e)	MUR 3,559

BMW X6

BMW X6 F16 (30dx, 40dx)	MUR 3,956
BMW X6 G06 (40iX)	MUR 3,318

BMW iX

BMW I20 (ix40)	MUR 3,076
----------------	-----------

Price includes: Materials, Labour and VAT. Exchange rate: MUR 51 / EUR 1. All offers are based on rate mentioned above and subject to change based on currency fluctuations higher than 10%. Subject to error, misprint and alteration. Photo non-contractual. Validity: 30.06.23

Leal & Co. Ltd

Motorway M1, Pailles 11201 | Tel: 207 2454 / 207 2400 | Fax: 286 5541

E-Mail: bmwcustomerservice@lealgroup.mu