



CONDITION BASED SERVICE (CBS).

FRONT BRAKE.



- Replace brake pads and wear sensor
- Clean caliper cavities
- Replace brake disc if worn to recommended point (additional charges applicable)



THE 1

BMW F20 116i	MUR 17,536
BMW F20 118i	MUR 17,918
BMW F20LCI - 116d ed	MUR 17,918
BMW F20LCI - 118i	MUR 17,536
BMW F40 118i	MUR 19,183
BMW F70	MUR 18,838

THE 2

BMW F44	MUR 19,183
BMW F45 - 218i	MUR 19,183
BMW F74	MUR 18,838
BMW G42 - 220d	MUR 19,183
BMW U06 (All)	MUR 19,219

THE 3

BMW F30 - 316i	MUR 17,918
BMW F30 - 320i	MUR 17,536
BMW F30 - 320i ED	MUR 17,536
BMW F30 - 328i	MUR 17,996
BMW F30LCI - 318i	MUR 17,536
BMW F30LCI - 320i	MUR 17,536
BMW F30LCI - 330i	MUR 17,996
BMW G20 - 330e	MUR 19,183
BMW G20 - 330i	MUR 44,331

THE 4

BMW F3X - 420i	MUR 17,536
BMW G22 - 420d	MUR 19,183
BMW G22 - 330i	MUR 25,623
BMW G22-G23 - 430d	MUR 25,623
BMW G22-G23 - M440i	MUR 25,623
BMW G23 - 430i	MUR 32,638

THE 5

BMW G30 - 520i	MUR 19,528
BMW G30 - 530i - 530e	MUR 52,418
BMW G30 LCI - 520i	MUR 19,528
BMW G30 LCI - 530e	MUR 19,528
BMW G60 - 520i - 530e	MUR 19,873

THE 7

BMW G11 - G12 - 740e	MUR 32,983
BMW G12 LCI - 745LeX	MUR 32,983
BMW G70 - 740d	MUR 34,823

THE 8

BMW G16 - 840d	MUR 32,983
BMW G16 - 840i	MUR 32,983

THE X1

BMW F48 - 18i - 20i	MUR 18,801
BMW F48 LCI - 18i	MUR 19,183
BMW F48 - F39 LCI 25eX	MUR 19,183
BMW U11 - 18i	MUR 19,219
BMW U11 - 20i	MUR 19,219
BMW U11 - 23i	MUR 20,369
BMW U11 - 25e	MUR 19,219

THE X2

BMW F39 - 18i	MUR 18,801
BMW F39 - 20i	MUR 18,801

THE X3

BMW F25 - 20d	MUR 18,033
BMW F25 - 28i N20	MUR 18,033
BMW F25 - 28i N52	MUR 18,033
BMW F25 - 30d	MUR 31,143
BMW G01 - 30e	MUR 23,093
BMW G01 LCI - 20iX	MUR 19,183
BMW G01 - M40i	MUR 32,638
BMW G01 - G02 - 20i	MUR 19,183
BMW G01 - G02 - 30i	MUR 26,543
BMW G01 LCI - 18d	MUR 19,183
BMW G01 LCI - 20d	MUR 32,638
BMW G01 LCI - xDrive30e	MUR 32,638
BMW G01 LCI - G02 LCI - 30d	MUR 32,638
BMW G45 - 20xDrive	MUR 4,923
BMW G45 - 30e	MUR 17,573
BMW G45 - M50	MUR 32,523

Price includes: Materials, Labour and VAT. Exchange rate: MUR 55 / EUR 1. All offers are based on rate mentioned above and subject to change based on currency fluctuations higher than 10%. Subject to error, misprint and alteration. Photo non-contractual. Validity: 31.12.2026



CONDITION BASED SERVICE (CBS).

FRONT BRAKE.



- Replace brake pads and wear sensor
- Clean caliper cavities
- Replace brake disc if worn to recommended point (additional charges applicable)



THE X4

BMW F26 - 20iX	MUR 18,033
BMW F26 - 28iX	MUR 31,143
BMW G02 LCI - 20iX	MUR 32,638
BMW G02 LCI - 30i	MUR 19,298

THE X5

BMW F15 - 25dX	MUR 21,598
BMW F15 - 30dX	MUR 21,598
BMW F15 - 40e	MUR 21,598
BMW G05 - 30D	MUR 74,153
BMW G05 - 40i	MUR 74,153
BMW G05 - 45e	MUR 32,638
BMW G05 - M50D	MUR 32,638
BMW G05 LCI - 30d	MUR 19,183
BMW G05 LCI - 50e	MUR 32,638

THE X6

BMW F16 - 30dX	MUR 22,276
BMW F16 - 40dX	MUR 22,276
BMW G06 - 40iX	MUR 32,638

THE iX1

BMW iX1 - eDrive20	MUR 19,219
BMW iX1 - xDrive	MUR 19,219

THE iX2

BMW iX2 - U10 sDrive 20i	MUR 19,219
--------------------------	------------

THE iX3

BMW G08 LCI BEV	MUR 19,945
-----------------	------------

THE iX4

BMW i20 - iX40	MUR 32,983
----------------	------------

THE i3

BMW i01 - i3	MUR 16,768
BMW i01 - i3S	MUR 16,768

THE i4

BMW G26 - i4 40	MUR 23,395
BMW G26 - i4 M50 - eDrive 35	MUR 28,613

THE i5

BMW G60 - i5 eDrive 40	MUR 31,706
BMW G60 - i5 M60	MUR 35,501

THE i7

BMW G70 - i7 xDrive60 - eDrive50	MUR 35,501
----------------------------------	------------

Price includes: Materials, Labour and VAT. Exchange rate: MUR 55 / EUR 1. All offers are based on rate mentioned above and subject to change based on currency fluctuations higher than 10%. Subject to error, misprint and alteration. Photo non-contractual. Validity: 31.12.2026