



CONDITION BASED SERVICE (CBS).

BRAKE FLUID.



- Replace brake fluid



THE 1

BMW F20 116i	MUR 4,793
BMW F20 118i	MUR 4,793
BMW F20LCI 116d ed	MUR 4,793
BMW F20LCI 118i	MUR 5,174
BMW F40 118i	MUR 4,411
BMW F70	MUR 4,411

THE 2

BMW F44	MUR 4,411
BMW F45 218i	MUR 4,793
BMW F74	MUR 4,411
BMW G42 220d	MUR 4,411
BMW U06 all	MUR 5,555

THE 3

BMW F30 316i	MUR 5,174
BMW F30 320i	MUR 5,174
BMW F30 320i ED	MUR 5,174
BMW F30 328i	MUR 5,174
BMW F30LCI 318i	MUR 5,174
BMW F30LCI 320i	MUR 5,174
BMW F30LCI 330i	MUR 5,174
BMW G20 330e	MUR 4,411
BMW G20 330i	MUR 5,174

THE 4

BMW F3X 420i	MUR 5,174
BMW G22 420d	MUR 4,411
BMW G22 430i	MUR 4,411
BMW G22-G23 430d	MUR 4,411
BMW G22-G23 M440i	MUR 4,411
BMW G23 430i	MUR 4,411

THE 5

BMW G30 520i	MUR 4,411
BMW G30 530i,530e	MUR 4,411
BMW G30 LCI 520i	MUR 4,411
BMW G30 LCI 530e	MUR 4,411
BMW G60 520i-530e	MUR 4,411

THE 7

BMW G11, G12 740e	MUR 6,318
BMW G12 LCI 745LeX	MUR 6,318
BMW G70 740d	MUR 4,411

THE 8

BMW G16 840d	MUR 4,411
BMW G16 840i	MUR 4,411

THE X1

BMW F48 18i,20i	MUR 4,793
BMW F48 LCI 18i	MUR 4,411
BMW F48, F39 LCI 25 eX	MUR 4,411
BMW U11 18i	MUR 5,555
BMW U11 20i	MUR 5,555
BMW U11 23i	MUR 5,555
BMW U11 25e	MUR 5,174

THE X2

BMW F39 18i	MUR 5,936
BMW F39 20i	MUR 5,936

THE X3

BMW F25 20d	MUR 4,793
BMW F25 28i N20	MUR 4,411
BMW F25 28i N52	MUR 4,411
BMW F25 30d	MUR 4,411
BMW G01 30e	MUR 4,411
BMW G01 LCI 20iX	MUR 4,411
BMW G01 M40i	MUR 4,411
BMW G01,G02 20i	MUR 4,411
BMW G01,G02 30i	MUR 4,411
BMW G01LCI 18d	MUR 4,411
BMW G01LCI 20d	MUR 4,411
BMW G01LCI xDrive30e	MUR 4,411
BMW G01LCI-G02LCI 30d	MUR 4,411
BMW G45 20xDrive	MUR 4,411
BMW G45 30e	MUR 4,411
BMW G45 M50	MUR 4,411

Price includes: Materials, Labour and VAT. Exchange rate: MUR 55 / EUR 1. All offers are based on rate mentioned above and subject to change based on currency fluctuations higher than 10%. Subject to error, misprint and alteration. Photo non-contractual. Validity: 31.12.2026

Leal & Co. Ltd

Motorway M1, Pailles 11201 | Tel: 207 2454 / 207 2400 | Fax: 286 5541

E-Mail: bmwcustomerservice@lealgroup.mu



CONDITION BASED SERVICE (CBS).

BRAKE FLUID.



- Replace brake fluid



THE X4

BMW F26 20iX	MUR 4,411
BMW F26 28iX	MUR 4,411
BMW G02 LCI 20iX	MUR 4,411
BMW G02LCI 30i	MUR 4,411

THE X5

BMW F15 25d(X)	MUR 4,411
BMW F15 30dX	MUR 4,411
BMW F15 40e	MUR 5,555
BMW G05 30D	MUR 4,411
BMW G05 40i	MUR 5,555
BMW G05 45e	MUR 6,318
BMW G05 M50D	MUR 4,411
BMW G05LCI 30d	MUR 4,411
BMW G05LCI 50e	MUR 4,411

THE X6

BMW F16 30dX	MUR 5,090
BMW F16 40dX	MUR 5,090
BMW G06 40iX	MUR 6,318

THE X7

BMW G07 M50d	MUR 4,411
BMW G07 M50i	MUR 4,411
BMW G07LCI 30d	MUR 4,411
BMW G07LCI 40d	MUR 4,411
BMW G07LCI 40i	MUR 4,411
BMW G07LCI M60i	MUR 4,411

THE i3

BMW I01 I3	MUR 4,411
BMW I01 I3S	MUR 4,411

THE i4

BMW G26 i4 40	MUR 5,174
BMW G26 i4 M50-eDrive35	MUR 5,174

THE i5

BMW G60 i5 eDrive40	MUR 5,852
BMW G60 i5 M60	MUR 5,852

THE i7

BMW G70 i7 xDrive60-eDrive50	MUR 5,852
------------------------------	-----------

THE iX1

BMW iX1 eDrive20	MUR 5,174
BMW iX1 xDrive30	MUR 5,174

THE iX2

BMW U10 sDrive 20i	MUR 5,555
--------------------	-----------

THE iX3

BMW G08LCI BEV	MUR 6,318
----------------	-----------

THE iX40

BMW I20 iX40	MUR 6,699
--------------	-----------

THE iX50

BMW I20 iX50	MUR 5,174
--------------	-----------

Price includes: Materials, Labour and VAT. Exchange rate: MUR 55 / EUR 1. All offers are based on rate mentioned above and subject to change based on currency fluctuations higher than 10%. Subject to error, misprint and alteration. Photo non-contractual. Validity: 31.12.2026

Leal & Co. Ltd

Motorway M1, Pailles 11201 | Tel: 207 2454 / 207 2400 | Fax: 286 5541

E-Mail: bmwcustomerservice@lealgroup.mu