



CONDITION BASED SERVICE (CBS).

MICRO FILTERS



- Replace Micro Filter / Pollen Filter



BMW 1 Series

BMW 1 Series F20 (116d ED LCI)	MUR 6,256
BMW 1 Series F20 (118i LCI)	MUR 6,486
BMW 1 Series F20 (116i, 118i)	MUR 6,486
BMW 1 Series F40 (118i)	MUR 6,946

BMW 2 Series

BMW 2 Series F45 (218i)	MUR 6,371
-------------------------	-----------

BMW 3 Series

BMW 3 Series F30 (318i LCI, 320i LCI)	MUR 6,486
BMW 3 Series F30 (330i LCI)	MUR 6,486
BMW 3 Series F30 (316i)	MUR 6,486
BMW 3 Series F30 (320i ED)	MUR 6,486
BMW 3 Series F30 (320i, 328i)	MUR 6,486
BMW 3 Series G20 (330i)	MUR 9,016

BMW 4 Series

BMW 4 Series F3X (420i)	MUR 6,486
-------------------------	-----------

BMW 5 Series

BMW 5 Series G30 (520i, 530i, 530e)	MUR 11,661
-------------------------------------	------------

BMW X1

BMW X1 F48 (18i, 20i)	MUR 6,371
BMW X1 F49 (18i, 20i)	MUR 6,371

BMW X2

BMW X2 F39 (18i, 20i)	MUR 6,285
-----------------------	-----------

BMW X3

BMW X3 F25 (28i N52)	MUR 10,799
BMW X3 F25 (28i N20)	MUR 10,799
BMW X3 G01 (20i, 30i)	MUR 9,061
BMW X3 F25 (20d, 30d)	MUR 10,592

BMW X4

BMW X4 F26 (20i, 28i)	MUR 10,799
BMW X4 G02 (20i, 30i)	MUR 9,016

BMW X5

BMW X5 F15 (40e)	MUR 14,019
BMW X5 F15 (25d, 30d)	MUR 14,249
BMW X5 G05 (40i)	MUR 20,591
BMW X5 G05 (M50d, 30d)	MUR 25,346
BMW X5 G05 (45e)	MUR 11,661

BMW X6

BMW X6 F16 (30d, 40d)	MUR 14,858
-----------------------	------------

Price includes: Materials, Labour and VAT. Exchange rate: MUR 51.50 / EUR 1. All offers are based on rate mentioned above and subject to change based on currency fluctuations higher than 10%. Subject to error, misprint and alteration. Photo non-contractual. Validity: 31.12.21

Leal & Co. Ltd

Motorway M1, Pailles 11201

Tel: 207 2454 / 207 2400 | Fax: 286 5541

E-Mail: bmwcustomerservice@lealgroup.mu