



CONDITION BASED SERVICE (CBS).

BRAKE FLUID



- Replace Brake Fluid



BMW 1 Series

BMW 1 Series F20 (116d ED LCI)	MUR 3,292
BMW 1 Series F20 (118i LCI)	MUR 3,522
BMW 1 Series F20 (116i, 118i)	MUR 3,292
BMW 1 Series F40 (118i)	MUR 3,062

BMW 2 Series

BMW 2 Series F45 (218i)	MUR 3,292
-------------------------	-----------

BMW 3 Series

BMW 3 Series F30 (318i LCI, 320i LCI)	MUR 3,522
BMW 3 Series F30 (330i LCI)	MUR 3,522
BMW 3 Series F30 (316i, 320i, 328i)	MUR 3,522
BMW 3 Series F30 (320i ED)	MUR 3,522
BMW 3 Series G20 (330i)	MUR 3,522

BMW 4 Series

BMW 4 Series F3X (420i)	MUR 3,522
-------------------------	-----------

BMW 5 Series

BMW 5 Series G30 (520i, 530i, 530e)	MUR 3,062
-------------------------------------	-----------

BMW X1

BMW X1 F48 (18i, 20i)	MUR 3,292
BMW X1 F49 (18i, 20i)	MUR 3,292

BMW X2

BMW X2 F39 (18i, 20i)	MUR 3,982
-----------------------	-----------

BMW X3

BMW X3 F25 (28i N52, 28i N20)	MUR 3,062
BMW X3 G01 (20i, 30i)	MUR 3,062
BMW X3 F25 (20d)	MUR 3,034
BMW X3 F25 (30d)	MUR 2,821

BMW X4

BMW X4 F26 (20i)	MUR 2,979
BMW X4 F26 (28i)	MUR 3,062
BMW X4 G02 (20i, 30i)	MUR 3,062

BMW X5

BMW X5 F15 (40e)	MUR 3,752
BMW X5 F15 (25d, 30d)	MUR 3,062
BMW X5 G05 (40i)	MUR 3,752
BMW X5 G05 (M50d, 30d)	MUR 3,062
BMW X5 G05 (45e)	

BMW X6

BMW X6 F16 (30d, 40d)	MUR 3,672
-----------------------	-----------

Price includes: Materials, Labour and VAT. Exchange rate: MUR 51.50 / EUR 1. All offers are based on rate mentioned above and subject to change based on currency fluctuations higher than 10%. Subject to error, misprint and alteration. Photo non-contractual. Validity: 31.12.21

Leal & Co. Ltd

Motorway M1, Pailles 11201

Tel: 207 2454 / 207 2400 | Fax: 286 5541

E-Mail: bmwcustomerservice@lealgroup.mu