



CONDITION BASED SERVICE (CBS).

AIR FILTER



- Air Filter replaced periodically



BMW 1 Series

BMW 1 Series F20 (116d ED LCI)	MUR 5,555
BMW 1 Series F20 (118i LCI)	MUR 3,772
BMW 1 Series F20 (116i, 118i)	MUR 3,772
BMW 1 Series F40 (118i)	MUR 4,577

BMW 2 Series

BMW 2 Series F45 (218i)	MUR 4,577
-------------------------	-----------

BMW 3 Series

BMW 3 Series F30 (318i LCI)	MUR 3,772
BMW 3 Series F30 (320i LCI)	MUR 4,290
BMW 3 Series F30 (330i LCI)	MUR 4,290
BMW 3 Series F30 (316i)	MUR 3,772
BMW 3 Series F30 (320i ED)	MUR 3,772
BMW 3 Series F30 (320i, 328i)	MUR 3,772
BMW 3 Series G20 (330i)	MUR 3,151

BMW 4 Series

BMW 4 Series F3X (420i)	MUR 4,290
-------------------------	-----------

BMW 5 Series

BMW 5 Series G30 (520i, 530i, 530e)	MUR 4,520
-------------------------------------	-----------

BMW X1

BMW X1 F48 (18i, 20i)	MUR 4,577
BMW X1 F49 (18i, 20i)	MUR 4,577

BMW X2

BMW X2 F39 (18i, 20i)	MUR 4,577
-----------------------	-----------

BMW X3

BMW X3 F25 (28i N52)	MUR 4,347
BMW X3 F25 (28i N20)	MUR 4,347
BMW X3 G01 (20i, 30i)	MUR 4,750
BMW X3 F25 (20d)	MUR 5,440
BMW X3 F25 (30d)	MUR 5,440

BMW X4

BMW X4 F26 (20i, 28i)	MUR 4,577
BMW X4 G02 (20i, 30i)	MUR 4,750

BMW X5

BMW X5 F15 (40e)	MUR 4,635
BMW X5 F15 (25d)	MUR 5,670
BMW X5 F15 (30d)	MUR 5,612
BMW X5 G05 (40i)	MUR 4,520
BMW X5 G05 (M50d, 30d)	MUR 4,520
BMW X5 G05 (45e)	MUR 4,520

BMW X6

BMW X6 F16 (30d, 40d)	MUR 6,222
-----------------------	-----------

Price includes: Materials, Labour and VAT. Exchange rate: MUR 51.50 / EUR 1. All offers are based on rate mentioned above and subject to change based on currency fluctuations higher than 10%. Subject to error, misprint and alteration. Photo non-contractual. Validity: 31.12.21

Leal & Co. Ltd

Motorway M1, Pailles 11201

Tel: 207 2454 / 207 2400 | Fax: 286 5541

E-Mail: bmwcustomerservice@lealgroup.mu